

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 1 720 East 3rd Avenue (Residence).

Direction: North

Date: 2/24/14

Time: 12:51




Photo 2 Common area "pathway" below stairwell.

Direction: Down

Date: 2/22/14

Time: 10:34

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck

(b) (6)



Photo 3 Common area looking north towards bedrooms and tool room.

Direction: North

Date: 2/22/14

Time: 10:49

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 4 Hallway to utility room, and dryer.

Direction: East

Date: 2/22/14

Time: 10:49

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 5 OSC Whittier, space heater, tool room in rear.

Direction: North

Date: 2/22/14

Time: 10:49

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck

(b) (6)



Photo 6 "Artwork" Bedroom.

Direction: West

Date: 2/22/14

Time: 10:49

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 7 Washer and sink in utility room. Note electrical top right & popcorn paint wall coating.

Direction: Northeast

Date: 2/22/14

Time: 10:50

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 8 Painted concrete floor in utility room with throw rug.

Direction: Down

Date: 2/22/14

Time: 10:50

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 9 Toilet.

Direction: West

Date: 2/22/14

Time: 10:50

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020

(b) (6)



Photo 10 Shower & personal storage.

Direction: Northwest

Date: 2/22/14

Time: 10:50

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 11 Water heater in utility room.

Direction: Northwest

Date: 2/22/14

Time: 10:50

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 12 Miscellaneous derelict electrical.

Direction: Up

Date: 2/22/14

Time: 10:52

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 13 Space heater.

Direction: Northeast

Date: 2/22/14

Time: 10:52

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020

(b) (6)



Photo 14 (b) (6) room.

Direction: Northeast

Date: 2/22/14

Time: 10:53

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overbeck

(b) (6)



Photo 15 North bedroom.

Direction: West

Date: 2/22/14

Time: 10:54

(b) (6)



Photo 16 (b) room.

Direction: East

Date: 2/22/14

Time: 10:54

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020

(b) (6)



Photo 17 (b) oom.

Direction: South

Date: 2/22/14

Time: 10:54

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck

(b) (6)



Photo 18 Carpet (b) (6) " bedroom.

Direction: Down

Date: 2/22/14

Time: 10:56

(b) (6)



Photo 19 (b) (6) " bedroom.

Direction: West

Date: 2/22/14

Time: 10:56

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck




Photo 20 Miscellaneous derelict electrical.

Direction: Up

Date: 2/22/14

Time: 10:57

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 21 OSC Whittier on stairwell.

Direction: South

Date: 2/22/14

Time: 11:00

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 22 Sewer pipe from above. Note popcorn paint.

Direction: South/Up

Date: 2/22/14

Time: 11:01



Photo 23 Miscellaneous derelict electrical.

Direction: Up

Date: 2/22/14

Time: 11:01

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 24 OSC Whittier & owner (b) (6) viewing location of master bedroom addition and crawl space external access point.

Direction: North

Date: 2/22/14

Time: 11:04



Photo 25 Utility room windows.

Direction: Down

Date: 2/22/14

Time: 11:04

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

720 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 26 Tool room window.

Direction: Down

Date: 2/22/14

Time: 11:05
